

## NIGERIAN CIVIL AVIATION AUTHORITY

P.M.B. 21029, 21038, IKEJA-LAGOS.

## **ALL OPERATORS LETTER (FSG 003)**

Ref:

NCAA/FSG/AOL/19/003

Date:

30th July, 2019

To:

All Aircraft Operators

From:

Nigerian Civil Aviation Authority

Attn:

Director of Flight Operations/Chief Pilot/Safety Manager

Subject:

CONTINUOUS OVERWRITING OF COCKPIT VOICE RECORDER (CVR) INFORMATION

The purpose of this FSG All Operators Letter (AOL) is to alert all aircraft operators on the continuous overwriting of Cockpit Voice Recorder (CVR) Information by their flight crew members and the necessity to ensure compliance with the appropriate Nigeria Civil Aviation Regulations (Nig. CARs) requirements.

## **Background**

The Nigerian Civil Aviation Authority (NCAA) has noticed that airline operators' flight crew members are in the practice of continuously overwriting the CVR information. This practice makes it impossible for the Accident Investigation Bureau (AIB) to retrieve actual data to aid in its investigation as required by Paragraphs 25 and 26 of the Civil Aviation (Investigation of Air Accidents and Incidents) Regulations 2019. This action had also impeded and posed undesirable difficulty in ensuring that AIB successfully discharge its statutory mandate of investigating accidents and serious incidents.

Nig. CARs Part 7.8.1.3 (b), which is derived from the provisions of ICAO Annex 6, Section 11.6 states that, "To preserve flight recorder records, flight recorders shall be deactivated upon completion of flight time following an accident or incident. The flight recorders shall not be reactivated before their disposition as determined in accordance with the accident/incident regulations of Nigeria".

<u>Furthermore, Nig. CARs Part 8.14.10.3</u> (a) requires that "The operator/owner of the aircraft, or in the case where it is leased, the lessee, shall ensure, to the extent possible, in the event the aircraft becomes involved in an accident or incident, the preservation of all related flight recorder records and, if necessary, the associated flight recorders, and their retention in safe custody pending their disposition as determined by the Accident Investigation Bureau.

The operational requirement of the flight recorders by the flight crew as detailed in Nig. CARs. Part 8.5.1.24 (b) and (c) require that "The PIC may not permit a flight data recorder or cockpit voice recorder to be disabled, switched off or erased during flight, unless necessary to preserve the data for an accident or incident investigation" and "In event of an accident or incident, the PIC shall act to preserve the recorded data for subsequent investigation upon completion of flight" respectively.



## **Actions Required:**

All operators of aircraft with CVR installed are hereby required to:

- 1. Conduct in-house awareness training for their flight crews on the requirements of Nig. CARs Parts 7.8.1.3 (b), 8.14.10.3 (a) and 8.5.1.24 (b) and (c) immediately on receipt of this AOL;
- 2. Develop/Emphasize appropriate procedures addressing the requirements of Nig. CARs Parts 7.8.1.3 (b), 8.14.10.3 (a) and 8.5.1.24 (b) and (c) and incorporate same in their respective Operations Manual. This amendment must be submitted to the Authority for review, acceptance and approval within thirty (30) days from the date of issue of this AOL. These procedures must form part of the contents of the Indoctrination training for flight crew members; and
- 3. Ensure continuous compliance with the requirements of the Nig. CARs on the preservation of flight recorder records.

The Authority will apply its enforcement processes, where non-compliances to the requirements of the Nig. CARs or non-conformance to the operator's approved procedures have been noticed.

Please, comply accordingly.

Capt. A.M. Sidi

**Director, Operations and Training** 

For: Director General.